


STRUCTURAL STABILITY CERTIFICATE

On the basis of visual inspection and the results of the Non-destructive Tests performed on the building of "Sultan-Ul-Uloom Public School", "Mount Pleasant", 8-2-249 to 267, Road No. 3, Banjara Hills, Hyderabad, Telangana State, it is found that the existing structure is safe and stable and fit for its intended occupation. However the structure should be periodically inspected for structural stability. Visual inspection shows that the condition of the building is satisfactory. No major distress or loss of structural integrity was observed. Until no major problems are noticed in the structure, it is suggested that structural evaluation should be carried out after 5 years to detect any deterioration if any.

Date : 23.07.2019

Chief Co-ordinator, I.C.S.



PRINCIPAL
SULTAN -UL-ULOOM PUBLIC SCHOOL
Banjara Hills, Hyderabad - 500 034.