BUILDING SAFETY CERTIFICATE

7	0
IV	()

Dated: 3-July-2024

It is certified that the existing building Mount Pleasant, H. No.8-2-249 to 267, Road No.3, (name of the building or premises) at Sultan-ul-Uloom Public School, Banjara Hills, Hyderabad – 34. (address) is having block(s) / Floor(s) as per details below:

Detail of Block(s) in school	Block(1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
Ground	2038.57			Canada .	~	
Floor	Sq. Mtrs.					8
1 st Floor	1887.14			70		
	Sq. Mtrs.	-		_		
2 nd Floor	1887.14					
	Sq. Mtrs.				1 (0.1	

The building is owned/occupied by Sultan-ul-Uloom Public School (name of the Institution) have complied with the Building safety requirements in accordance with national Building code Rules, and verified by the officers concerned of Municipality (Name of Department / Govt.) on 3/7/2029.....(date of inspection) in the presence of

ten-ul-ulgom publics had addresses of the Manager / Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from .. 20.24...... for a period of . 20.26..... years in accordance with rule and subject to compliance of the specific conditions as appended.

1.																•	•
2.								 					•				•
3.								 • •	 				0				•
4.								• • •									•
Issued	on	4.	Ju	J.	1.:	les.	19	at	. 1	1.	7.0	d	5	γ.	C	V	b.adBy
				9	1												In case of blo

*Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

Name: G. SRINIVASA RAO, M. Tech (Structures) (Structural Engineer)

Designation: No: 442/Strl Engineer/TP10/GHMC/2009

Name & Address of Department / Office:

SULTAN UL-ULOOM PUBLIC SCHOOL Banjara Hills, Hyderabad-500 034